

Quandary of the Quirky Quadrupole

Alan Cooper (ANU) Australia

Water cooled coils corroded through leading to an episode of coil changes, failure leading to more coil changes and the eventual air cooling of the quadrupole in question. Information gained leaves us in a position to meet the next coil failure with confidence.